VIRGINIA

HIGHWAY

SAFETY

2922

SUMMIT





SUPERIOR SECURE SAVING SERVICE CREDENTIALS LIVES

The Commission on Virginia Alcohol Safety Action Program

1111 E. Main St. Suite 801 Richmond, VA 23219 (804) 786-5895



Your Doorway to Safe & Sober Driving

vasap.virginia.gov



• Ignition Interlock Vendors – Drager, Intoxalock, LifeSafer & Smart Start

• Ignition Interlock Regulations

- Tight regulatory requirements
- Interlock facility within a 50-mile radius of every Virginia resident
- Monitoring of customer complaints
- Set wait time minimums
- Interlock device certification
- Technician certification
- INSPIRE (Integrated, National, Standardized, Participatory, Interlock, Reciprocity, Exchange)



Interlock Installation

- 30 day requirement
- 1-2 business day maximum install wait time
- Eligible to be installed on a non-owned vehicle
- Only court can permit operation of employment vehicle w/o interlock device installed
- Install on motorcycles and mopeds
- Camera required
- Pre and post installation checklist
- \$65-\$130 install fee
- Breath reductions
- Indigent status



- Interlock Requirement Duration
 - DMV Administrative minimum six-consecutive months with no alcohol-related violations.
 - Court Requirement set by the court of jurisdiction with a minimum of six-consecutive months with no alcohol-related violations.
 - 12-month interlock requirement (no early removal) with no other restrictions if BAC less than .15% and court approves.
 - Interlock and remote alcohol device for length of interlock period with no other restrictions if BAC was .15% or higher on a DUI 1st offense or any 2nd or subsequent offense. Also dependent on court approval.



Interlock Calibration

- At least every 30 days.
- Tightest requirement in the country
- \$95 per month not including taxes and \$8 optional insurance
- Interlock Violations
 - 0.02% BAC or greater
 - Provide 15-minute re-test period.
 - First fail 5 minute lock-out, 2nd fail 10 minute
 - Rolling re-test prompts randomly within 10-15 minutes after start of the vehicle and then randomly every 60 minutes afterwards. 15 minutes to provide test.
 - Low-level BAC violations require secondary review





8/31/2018 10:49:13 PM

98858

Initial Test Passed

0.000 g/210L

• Interlock Removal

- Requires ASAP authorization
- Pre and post removal inspection checklist.
- \$0 removal fee
- Interlock Circumventions & Tampering
 - Manipulation of BAC readings (cologne, etc...)
 - Jumping the starter
 - Using friends, family member and children to start the vehicle
 - Processing circumvention violations



7/26/2018 8:00:43 AM

47855

Initial Test Failed

0.030 g/210L



Initial Test Not Delivered



7/26/2018 8:06:23 AM

47863

Initial Test Failed

0.028 g/210L

8/16/2018 1:32:59 PM

7044

Retest Passed

0.000 g/210L

8/16/2018 2:35:02 PM 7064 Initial Test Failed

0.086 g/210L

:40:51 PM Initial Test Passed 0.000 g/210L


8/16/2018 3:07:14 PM

7117

Vehicle Movement Begins

8/16/2018 2:4
7075







05/26/2018 06:06:04 PM

ENGINE ON 05/26/2018 05:34:42 PM



RETEST PRSS 0.000 05/26/2018 05:26:47 PM

7/16/2018 4:52:29 PM

55635

Vehicle Movement Begins

7/17/2018 7:54:24 AM 55661 Initial Test Failed

0.022 g/210L

7/17/2018 7:59:24 AM

55664

Initial Test Not Delivered









Ignition Interlock Device Demonstration

Demonstration by Smart Start on the different components of the ignition interlock system and its functionality.



The Commission on Virginia Alcohol Safety Action Program

1111 E. Main St. Suite 801 Richmond, VA 23219 (804) 786-5895



Your Doorway to Safe & Sober Driving

vasap.virginia.gov

